

EPA ID: NJD986607752 Site Name: EXXON SERVICE STATION #3-2558

State ID:

Alias Site Names:

City: BRANCBURG TWP

County or Parish: SOMERSET

State: NJ

Refer to Report Dated: 06/17/2003

Report Type: PRELIMINARY ASSESSMENT 001

Report Developed by: DEP

DECISION:

☐ 1. Further Remedial Site Assessment under CERCLA (Superfund) is not required because:

☐ 1a. Site does not qualify for further remedial site assessment under CERCLA (No Further Remedial Action Planned - NFRAP)

☐ 1b. Site may qualify for action, but is deferred to:

☒ 2. Further Assessment Needed Under CERCLA:

2a. Priority: ☒ Higher ☐ Lower

2b. Other: (recommended action) High

DISCUSSION/RATIONALE:

Since 1967, Humble Oil owned this site and operated a gasoline service station and auto repair shop. A 1966 plot plan depicts an onsite service center, a 550 gal waste oil tank, a 1000 gal septic tank, and an approx. 800 square ft leach field with a diverter box to the northeast of the building. USTs and the waste oil tank were removed in 1987. No post excavation soil sampling was conducted. A 1988 letter from ExxonMobile indicates the presence of stockpiled soil from the area of the waste oil tank. A 1999 NJDEP inspection noted sealed floor drains in the service center. It is unknown where these pipes discharged to. A deep well installed onsite by ExxonMobile indicates contamination of TCE.

Local sampling of potable wells indicate the presence of TCE. A site inspection is recommended to further delineate the groundwater pathway.

Site Decision Made by: KRISTIN DOBINSON

Signature: Kristin Dobinson

Date: 09/10/2003

